

# **ULINE** H-915 INDUSTRIAL HEAT GUN

1-800-295-5510  
uline.com



## TROUBLESHOOTING

OPERATING ISSUE	RECOMMENDATIONS
Gun is not turning on.	If the gun has been used recently the internal thermostat may be keeping the gun from turning on. Allow the gun to cool for 20-30 minutes and try again.
Gun is blowing only cool air.	Adjust the dial on the back of the unit.

**ULINE H-915**  
**PISTOLA DE CALOR**  
**INDUSTRIAL**

01-800-295-5510  
uline.mx



**SOLUCIÓN DE PROBLEMAS**

<b>PROBLEMA DE FUNCIONAMIENTO</b>	<b>RECOMENDACIONES</b>
La pistola no enciende.	Si la pistola se ha usado recientemente, puede que el termostato interno esté evitando que la pistola encienda. Deje que la pistola se enfríe entre 20-30 minutos e inténtelo de nuevo.
La pistola solo emite aire frío.	Ajuste el disco ubicado en la parte posterior de la unidad.

**ULINE H-915**  
**PISTOLET THERMIQUE**  
**INDUSTRIEL**

1-800-295-5510  
uline.ca



## DÉPANNAGE

PROBLÈME	RECOMMANDATIONS
Le pistolet ne s'allume pas.	Si le pistolet a récemment été utilisé, le thermostat interne peut empêcher le pistolet de s'allumer. Laissez le pistolet refroidir pendant 20 à 30 minutes, puis réessayez.
Le pistolet ne souffle que de l'air frais.	Réglez la molette à l'arrière de l'appareil.